

Spills to the Sea
April 1, 2015 - March 31, 2016

<i>Date of Incident</i>	<i>Type of Discharge</i>	<i>Substance Released</i>	<i>Volume (Liters)</i>	<i>Operator</i>	<i>Installation/Vessel</i>	<i>Source</i>
20-Apr-15	Spill	Condensate	0.0042	ExxonMobil-SOEP	Venture	Flare vapour
19-Jun-15	Spill	Hydraulic Oil	0.073	ExxonMobil-SOEP	South Venture	Corroded end cap on a hydraulic actuator
20-Jul-15	Spill	Unknown	0.007	ExxonMobil-SOEP	Thebaud Compression	Unknown
31-Jul-15	Spill	Hydraulic Oil- EnviroLogic 122	0.950	EnCana	Atlantic Condor	Leak in wrist of ROV arm
06-Aug-15	Spill	Hydraulic Oil	90	ExxonMobil-SOEP	North Triumph	Failed hydraulic hose
22-Nov-15	Spill	Hydraulic Oil	0.01	ExxonMobil-SOEP	Thebaud	Corroded fitting on a hydraulic actuator on the condensate cooler