

Date of Incident	Substance Released	Volume (Litres)	Concentration (%_mg/L_ppm_ etc)	Operator	Installation/Vessel	Installation/Vessel Type	Source
05-Jun-20	Hydraulic Fluid - Terrasolve Envirologic 122	<1		Ovintiv Canada ULC	Noble Regina Allen	Rig	Damaged fitting on the remotely operated vehicle (ROV).
23-Jun-20	Hydraulic Fluid - Terrasolve Envirologic 122	<1		Ovintiv Canada ULC	Atlantic Condor	Stand-by/Supply Vessel	A flexiclean tool on the remotely operated vehicle (ROV).
22-Jul-20	Hydraulic Fluid - Terrasolve Envirologic 122	<1		Ovintiv Canada ULC	Atlantic Condor	Stand-by/Supply Vessel	A cracked supply tube on the remotely operated vehicle (ROV).
03-Aug-20	Hydraulic Fluid - Terrasolve Envirologic 122	<1		Ovintiv Canada ULC	Noble Regina Allen	Rig	Failed hose for Rigmaster Manipulator Shoulder Up function on the remotely operated vehicle (ROV).

Note: Unauthorized Discharge of a substance that is not contemplated in the Environmental Protection Plan (either the substance, or the circumstance of the release, is not contemplated)