



## Spills to the Sea

### April 1, 2018 - March 31, 2019

Updated: April 25, 2019

Date of Incident	Substance Released	Volume (Litres)	Operator	Installation/Vessel	Installation/Vessel Type	Source
29-Apr-18	Hydraulic Oil	131	ExxonMobil Canada Ltd.	Alma	Platform	Failed hydraulic hose
11-Jul-18	Hydraulic Oil	1.63	ExxonMobil Canada Ltd.	Noble Regina Allen	Rig	Hydraulic hose
13-Sep-18	Hydraulic Oil	2-3	Encana Corporation	Atlantic Condor	Stand-by/Supply Vessel	Azimuth thruster prop wash
19-Oct-18	Hydraulic Oil	<1	ExxonMobil Canada Ltd.	Noble Regina Allen	Rig	Fitting on the control panel
31-Oct-18	Hydrocarbon Sheen	<1	ExxonMobil Canada Ltd.	Noble Regina Allen	Rig	Sea water exchanger
02-Nov-18	Lubricating Oil	5-10	Encana Corporation	Atlantic Condor	Stand-by/Supply Vessel	Tube seal
06-Jan-19	Hydrocarbon Sheen	<1 mL	ExxonMobil Canada Ltd.	South Venture	Platform	The drum used to dispose of used absorbent pads was corroded.
19-Mar-19	Hydrocarbon Sheen	<1	ExxonMobil Canada Ltd.	Thebaud	Platform	Drains box witches hat
30-Mar-19	Hydraulic Oil	<1	ExxonMobil Canada Ltd.	Thebaud	Platform	Hydraulic pump discharge hose

*Note: a spill is any discharge of petroleum (including but not limited to crude oil, natural gas, condensate, lubricants, hydraulic oils, fuels, petroleum based synthetic drilling fluids, or any other refined petroleum product) that enters the sea in the offshore area other than one that is authorized under the Accord Acts or the Regulations must be reported as a spill.*