

Spills to the Sea
April 1, 2005 - March 31, 2006

| <i>Date of Incident</i> | <i>Substance</i> | <i>Volume (Liters)</i> | <i>Operator</i> | <i>Installation/Vessel</i> | <i>Source</i> |
|-------------------------|----------------------|------------------------|-----------------|----------------------------|----------------------------------|
| 10-Apr-05 | Hydraulic Oil | 65 | ExxonMobil-SOEP | Alma | Valve actuator assembly |
| 04-May-05 | Oil (unclassified) | <0.1 | ExxonMobil-SOEP | South Venture | Deck drainage |
| 10-May-05 | Hydraulic Oil | 97.5 | ExxonMobil-SOEP | Alma | Hydraulic oil system |
| 15-Jun-05 | Hydraulic Oil | 4 | ExxonMobil-SOEP | ROV | ROV hydraulic oil system |
| 28-Jun-05 | Oil (unclassified) | <0.1 | ExxonMobil-SOEP | South Venture | Bucket of produced water spilled |
| 11-Jul-05 | Condensate | <0.1 | ExxonMobil-SOEP | Venture | Pressure safety valve |
| 05-Aug-05 | Hydraulic Oil | 55 | ExxonMobil-SOEP | South Venture | Loose hydraulic line fitting |
| 29-Aug-05 | Oil (unclassified) | <0.1 | ExxonMobil-SOEP | Venture | Vent drum |
| 11-Nov-05 | Condensate | <0.1 | ExxonMobil-SOEP | Thebaud | Crudesorb unit |
| 02-Dec-05 | Hydraulic Oil | 5 | ExxonMobil-SOEP | South Venture | Condensate level control valve |
| 19-Dec-05 | Synthetic Based Mud | 0.2 | ExxonMobil-SOEP | Galaxy II | Mixed slops |
| 12-Jan-06 | Mono-ethylene Glycol | 130,000 - 158,00 | ExxonMobil-SOEP | Thebaud | MEG flowline |
| 18-Jan-06 | Hydraulic Oil | 0.2 | EnCana | Rowan Gorilla VI | Hydraulic line |